## **Post Drilling/Annual Well SiteInspection Form**

Section 1: General Information				
Operation Data	Inspection Data			
Operator Name	Inspector Name			
Snake River Oil + Gas, LLC	James Thum			
Well Name	Area Office			
ML Investments #2-10, USWN 11-075-20022 Authorized Contact: Dan Johanek (208)707-7867	Boise / Director's			
112 N. Plymouth, New Plymouth ID; Tyler Hartung (208)	Inspection Date 9/29/2022 1:45 PM			
412-5475	<i>JEJI2022</i> 1.43 1 WI			
County	Report Date			
Payette	10/4/2022			
Inspector's Signature:/signed/ James Thum	Inspection Summary:			
	Operation appeared to be in compliance at the time of the inspection.			
	Issues of concern identified at the time of	of the		
Date of Signature: 10/4/2022	inspection.			
<b>Location Description:</b> 1800 feet ESE from Little Willow Gathering Facility, 4649 Little Willow Road. Google Maps location Latitude 44.049326, Longitude -116.796756. Mike Shafer – Little Willow staff, contact thru Tyler.				
Weather: Sunny / hazy smoke, 70 degrees F. Slight variable wind				
Scope of Inspection (check all that apply and, or, were verified	ed during the inspection):			
Well site Tank Battery Wellhead Meters	Other:			
If well site, is the well a multiple zone completion?		🖂 No		
		_		
Section 2: Pits		20.07.02.230		
1. Are pits located on site?	Yes	🛛 No		
A. If yes;				
i. Permitted as:	Short-term pit			
ii. Use Corresponding Pit Inspection Form and attach with this inspection.				
	L L			
Section 3: Identification of Wells		20.07.02.300		
1. Is a lease access road sign visible where the principal	lease road enters the lease? $\square$ Yes	🗌 No		
A. If yes;				
i. Does the sign show:				
a. The name of the lease?	Xes	🗌 No		
b. The name of the owner or operator?	Xes	□ No		
		_		
c. The Section, Township and Range?				
2. Is a legible well site sign visible near the well?	🛛 Yes	🗋 No		
A. If yes;				
i. Does the well site sign identify the;				
a. Operator?	X Yes	🗌 No		
b. Permit number?	$\boxtimes$ Yes	 No		
c. Well name?	$\boxtimes$ Yes	□ No		
		_		
d. Emergency telephone number?	🖂 Yes	🗌 No		

3.	For multiple completions, is there a sign for each well head connection?	N/A Yes No
Sectio	on 4: Location Operations	IDAPA 20.07.02.301
1.	Is the well site fenced? (Answer N/A if the well has not been completed and fencing is not erected) A. If Yes;	🗌 N/A 🔀 Yes 🗌 No
	i. Was the fence installed within 60 days of completing the facility?	🛛 Yes 🗌 No
	ii. Does the fence appear to:	
	a. Maintain safe working conditions?	🛛 Yes 🗌 No
	b. Secure the well site?	🔀 Yes 🗌 No
	c. Prevent access by wildlife and livestock? See Comments Section	🛛 Yes 🗌 No
2.	Is there less than 5% vegetation on site?	🛛 Yes 🗌 No
3.	Has it been more than six months since the removal of the drilling rig? A. If No;	🛛 Yes 🗌 No
	i. Are chemicals stored and maintained in accordance with all applicable MSDS requirements?	🔀 N/A 🗌 Yes 🗌 No
	ii. Are all materials related to operations palletized?	N/A Yes No
	iii. Do all vehicles or materials on the site appear to be in use?	N/A Yes No
	iv. Is the site free from all trash, debris, or scrap metal on site?	🗌 Yes 🗌 No
	a. If no, is all trash, debris and scrap metal pending removal kept in a wind proof container and appear emptied regularly?	🛛 N/A 🗌 Yes 🗌 No
	b. If trash or debris constitutes a fire hazard, is it removed to at least 100 feet from the facility, tanks or separators?	🛛 N/A 🗌 Yes 🗌 No
	B. If Yes;	
	i. Are all debris and waste materials including, but not limited to, concrete, sack bentonite and other drilling mud additives, sand, plastic, pipe, and cable associated with the drilling and completion operations removed and disposed of properly?	🛛 Yes 🗌 No
	ii. Are all disturbed areas affected by drilling or subsequent operations, except areas reasonably needed for production operations or subsequent drilling operations within twelve months, reclaimed and revegetated to approximately the pre-drilling condition (in accordan with IDAPA 20.07.02.510.04-07 or to the condition specified in an	
	agreement with the surface owner.	Yes 🗌 No
Sectio	on 5: Accidents and Fires	IDAPA 20.07.02.302
1.	Is the emergency response plan available for use or inspection?	🛛 Yes 🗌 No
	A. If yes, does the operation appear to be consistent with the response plan?	🛛 Yes 🗌 No
2.	Is the location free of evidence of recent fires?	🛛 Yes 🗌 No
	A. If no, have they been properly reported?	🛛 N/A 🗌 Yes 🗌 No

3.	Ask for a spill prevention and countermeasures plan (SPCC can be located in company office). Are they aware of it?	🛛 Yes 🗌 No
Section	n 6: Chokes	IDAPA 20.07.02.312
	Are all flowing wells equipped with adequate chokes to properly control flow?	🗌 N/A 🛛 Yes 🗌 No
Section	n 7: Measurement of Gas	IDAPA 20.07.02.402
1.	Is the site a natural gas well?	🛛 Yes 🗌 No
	A. If yes, is there a standard industry meter approved by the American Gas Associa and capable of recordingaccurately the volume of natural gas produced at each v	
	<ul> <li>B. If no, is there another methodology being utilized that has been approved by the Department?</li> </ul>	🛛 N/A 🗌 Yes 🗌 No
	a. If yes, describe:	
2. Sepa	arator location and Meter System Location: Well Site Little Willow Gathering Facility Other:	
Section	n 8: Meters	IDAPA 20.07.02.410
1.	Type of Hydrocarbon Measuring Systems:	
	Coriolis Measuring System for Liquids 🗌 Orifice Measuring System for Gas	5
	Other:	
2.	Are meter fittings of adequate size to measure gas efficiently?	🛛 Yes 🗌 No
3.	Are meters accessible and viewable?	🛛 Yes 🗌 No
4.	Are valves installed so pressures can be readily obtained on both casing and tubing?	Yes 🗌 No
5.	Are yearly meter calibration records available for inspection?	🗌 N/A 🛛 Yes 🗌 No
Section	n 9: Tank Batteries	IDAPA 20.07.02.420
1.	Are there tank batteries located on site? A. If yes, are all tank batterieslocated at least 300 feet from any existing:	🗌 Yes 🕅 No
	<ul> <li>i. Occupied structures?</li> <li>N/A</li> </ul>	☐ Yes ☐No
	i. Water wells?	$\Box \operatorname{Yes} \Box \operatorname{No}$
	iii. Canals?	$\Box$ Yes $\Box$ No
	iv. Ditches?	☐ Yes ☐ No
	v. Natural or ordinary high water mark of surface waters?	🗌 Yes 🗌 No
	B. Is location at least 50 feet from highways when measured from outermost portion of the tank dike?	Yes No
	C. Are all tanks containing produced fluids or crude oil surrounded by tank dikes?	🗌 Yes 🗌 No
	D. Are all tanks equipped to receive produced fluids surrounded by tank dikes?	Yes No
	i. If yes;	
	a. Do the dikes have a capacity of at least 1 $\frac{1}{2}$ times the volume of the large	gest tank? 🗌 Yes 🗌 No
	b. Is all piping and manmade improvements that perforate the dike wall or	• tank


	y floor sealed to a minimum radius of 12" from outside edge of the piping provement?	🗌 Yes 🗌 No		
c. Are va	alves and quick-connect couplers at least 18" from inside wall of tank dike?	🗌 Yes 🗌 No		
d. Is veg	etation on top and outside surface properly maintained?	Yes No		
	lder or other permanent device installed over the tank dike to access the ment reservoir?	🗌 Yes 🗌 No		
	ainment reservoir free of vegetation, storm water, produced fluids, other oil s field related debris, trash or flammable material?	🗌 Yes 🗌 No		
E. Do drain lines	have a valve installed, closed and capped off if not in use?	Yes No		
Section 10: Inspection C	omments			
Comments and Issues of	Concern:			
Two entrance gates- SE gate not signed, closed; SW gate open, signed to the west. Fence keeps animals and livestock out of well area only when gate is closed.				
Cellar is gravel-filled, no v	vegetation on pad and well site is clean.			
Scavenger unit does not appear functional. Gauges not working, opaque tank so fill level uncertain. MSDS paper wet / rotted and needs replaced.				
Surface casing: 540 psi (a Production casing: 180 ps Tubing string: 526.2 psi (a	si (analog gauge)			
Pressure noted on all three	e casing strings – check for verification; possible MIT needed.			
9 photos from inspection i	n files.			

## Section 11: Attachments

List any and all attachments including photos, samples, documents, etc:

Well head and steel fence, view north-northeast.





Base of well head with gravel filled cellar.

