Post Drilling/Annual Well Site Inspection Form

Section 1: General Information	
Operation Data	Inspection Data
Operator Name Snake River Oil + Gas, LLC	Inspector Name James Thum
Well Name	Area Office
Kauffman #1-34, USWN 11-075-20024	Boise / Director's
Authorized Contact: Dan Johanek (208)707-7867 112 N.	Inspection Date
Plymouth, New Plymouth ID; Tyler Hartung (208) 412-5475	9/29/2022 9:10 AM
County Payette	Report Date 10/3/2022
Inspector's Signature: /signed/ James Thum	Inspection Summary:
	Operation appeared to be in compliance at the time of the inspection.
	☐ Issues of concern identified at the time of the
Date of Signature: 10/3/2022	inspection.
Location Description: 2.0 miles NNW from Little Willow Clocation Latitude 44.079257, Longitude -116.810886. Well re Weather: Clear, hazy smoke; 60 degrees F, no wind.	
Scope of Inspection (check all that apply and, or, were verifi	ed during the inspection):
🛛 Well site 🔲 Tank Battery 🔀 We	ellhead 🛛 Meters 🖂 Other: Separator Unit
If well site, is the well a multiple zone completion?	☐ Yes ⊠ No
Section 2: Pits	IDAPA 20.07.02.230
1. Are pits located on site?	☐ Yes ⊠ No
A. If yes;	
i. Permitted as:	Short-term pit
ii. Use Corresponding Pit Inspection Form and	attach with this inspection.
Section 3: Identification of Wells	IDAPA 20.07.02.300
1. Is a lease access road sign visible where the principal	l lease road enters the lease?
A. If yes;	
i. Does the sign show:	
a. The name of the lease?	
b. The name of the owner or operator?	☐ Yes ☐ No
•	
c. The Section, Township and Range?	⊠ Yes □ No
2. Is a legible well site sign visible near the well?	∑ Yes □ No
A. If yes;	
i. Does the well site sign identify the;	
a. Operator?	∑ Yes □ No
b. Permit number?	
c. Well name?	∑ Yes □ No
d. Emergency telephone number?	— Yes ☐ No
3. For multiple completions, is there a sign for each wel	

Section 20.07.0	n 4: Location Operations	IDAPA
	Is the well site fenced? (Answer N/A if the well has not been completed and fencing is not erected) A. If Yes;	□ N/A ⊠ Yes □ No
	i. Was the fence installed within 60 days of completing the facility?	⊠ Yes □ No
	ii. Does the fence appear to:	
	a. Maintain safe working conditions?	∑ Yes No
	b. Secure the well site?	∑ Yes ☐ No
	c. Prevent access by wildlife and livestock? See Section 10 Comments	∑ Yes No
2.	Is there less than 5% vegetation on site?	☐ Yes ⊠ No
3.	Has it been more than six months since the removal of the drilling rig? A. If No;	⊠ Yes □ No
	i. Are chemicals stored and maintained in accordance with all applicable MSDS requirements?	N/A ☐ Yes ☐ No
	ii. Are all materials related to operations palletized?	⊠ N/A □ Yes □ No
	iii. Do all vehicles or materials on the site appear to be in use?	⊠ N/A □ Yes □ No
	iv. Is the site free from all trash, debris, or scrap metal on site?	☐ Yes ☐ No
	a. If no, is all trash, debris and scrap metal pending removal kept in a wind proof container and appear emptied regularly?	N/A ☐ Yes ☐ No
	b. If trash or debris constitutes a fire hazard, is it removed to at least 100 feet from the facility, tanks or separators?	⊠ N/A □ Yes □ No
	B. If Yes;	
	i. Are all debris and waste materials including, but not limited to, concrete, sack bentonite and other drilling mud additives, sand, plastic, pipe, and cable associated with the drilling and completion operations removed and disposed of properly?	⊠ Yes □ No
	ii. Are all disturbed areas affected by drilling or subsequent operations, except areas reasonably needed for production operations or subsequent drilling operations within twelve months, reclaimed and revegetated to approximately the pre-drilling condition (in accordance with IDAPA 20.07.02.510.04-07 or to the condition specified in an	
	agreement with the surface owner.	⊠ Yes ∐ No
Section 20.07.0	n 5: Accidents and Fires 02.302	IDAPA
1.	Is the emergency response plan available for use or inspection?	⊠ Yes □ No
	A. If yes, does the operation appear to be consistent with the response plan?	∑ Yes ☐ No
2.	Is the location free of evidence of recent fires?	Yes No
	A. If no, have they been properly reported?	⊠ N/A □ Yes □ No

3	. Ask for a spill prevention and countermeasures plan (SPCC can be located in company office). Are they aware of it?	⊠ Yes □ No
	on 6: Chokes 7.02.312	DAPA
		Yes No
	on 7: Measurement of Gas I	DAPA
1	. Is the site a natural gas well?	⊠ Yes □ No
	A. If yes, is there a standard industry meter approved by the American Gas Association and capable of recording accurately the volume of natural gas produced at each well?	⊠ Yes □ No
	B. If no, is there another methodology being utilized that has been approved by the Department?	Yes No
	a. If yes, describe:	
2.	Separator location and Meter System Location: Well Site	
Secti	on 8: Meters	DAPA
20.07	7.02.410	
1		
	☐ Coriolis Measuring System for Liquids ☐ Orifice Measuring System for Gas	
	Other:	
2		⊠ Yes ∐ No
3		Yes
4		Yes
3	. Are yearly meter calibration records available for inspection?	Yes No
	on 9: Tank Batteries I 7.02.420	DAPA
1	Are there tank batteries located on site?A. If yes, are all tank batteries located at least 300 feet from any existing:	☐ Yes ⊠ No
	i. Occupied structures?	☐ Yes ☐ No
	ii. Water wells?	☐ Yes ☐ No
	iii. Canals?	☐ Yes ☐ No
	iv. Ditches?	☐ Yes ☐ No
	v. Natural or ordinary high water mark of surface waters?	☐ Yes ☐ No
	B. Is location at least 50 feet from highways when measured from outermost portion of the tank dike?	☐ Yes ☐ No
	C. Are all tanks containing produced fluids or crude oil surrounded by tank dikes?	☐ Yes ☐ No
	D. Are all tanks equipped to receive produced fluids surrounded by tank dikes?	∑ Yes □ No
	i. If yes; Separator dike	
	a. Do the dikes have a capacity of at least 1 ½ times the volume of the largest tank?	⊠ Yes □ No

b. Is all piping and manmade improvements that perforate the dike wall or tank battery floor sealed to a minimum radius of 12" from outside edge of the piping or improvement?
c. Are valves and quick-connect couplers at least 18" from inside wall of tank dike? X Yes No
d. Is vegetation on top and outside surface properly maintained? Yes No
d. Is vegetation on top and outside surface property maintained:
e. Is a ladder or other permanent device installed over the tank dike to access the containment reservoir? Separator dike
f. Is containment reservoir free of vegetation, storm water, produced fluids, other oil and gas field related debris, trash or flammable material?
E. Do drain lines have a valve installed, closed and capped off if not in use?
Section 10: Inspection Comments
Comments and Issues of Concern: Fence and gate are functional, but signs of cattle activity are apparent on the well pad indicating the gate has been left open at some point.
Pad and fencing in need of weed remediation with vegetative covering >15% of the well pad, notably in the vicinity of the well head and south part of pad. Vegetation shows a marked increase from the 2021 inspection.
Well is currently shut-in; last reported production October 2021. ADD meter indicates 4614.59 BC produced 9/28, 110.557 BC produced 9/29. Readings may be in error?
Surface casing: 0 psi Production casing: 0 PSI Tubing string: 1299.9 psi (dig)

Section 11: Attachments

List any and all attachments including photos, samples, documents, etc:

Well pad from lease entrance, looking NW. Note vegetation in vicinity of well head.





Separator unit with SCADA remote in background.

1375 1375	PlatelCone Inspect (Date)	Orifice Bore Size	Beta Ratio	Meter Test (Date)	Gas Analysis (Date)	Specific Gravity	Tested By	
622-21 1.375 .47 10-20-21 NOFlow - BB 10-20-21 1.375 .47 10-20-21 NOFlow BB			0.474			0.7836	Mari	
10-20-21 1375 · 42 10-20-21 — KB		1,3/2	0,474		NO Flow	_	KB	
	6-22-21	P) make an			1101 100		KB	
zedisolutions.com, PHONE: (307) 856-0866	10.00.01	1.07		10 000				
zedisolutions.com, PHONE: (307) 856-0866								
zedisolutions.com, PHONE: (307) 856-0866								
zedisolutions.com, PHONE: (307) 856-0866								
zedisolutions.com, PHONE: (307) 856-0866								
zedisolutions.com, PHONE: (307) 856-0866								
zedisolutions.com, PHONE: (307) 856-0866								
zedisolutions.com, PHONE: (307) 856-0866								
	zedisolutions.co	om, PHONE: (307) 856-0866					
	zedisolutions.co	om, PHONE: (307	856-0866					
	zedisolutions.co	om, PHONE: (307	856-0866					
	zedisolutions.co	om, PHONE: (307	856-0866					
	zedisolutions.co	om, PHONE: (307	856-0866					
	zedisolutions.co	om, PHONE: (307	856-0866					
	zedisolutions.co	om, PHONE: (307	856-0866					
	zedisolutions.co	om, PHONE: (307	856-0866					
	zedisolutions.co	om, PHONE: (307	856-0866					

