Post Drilling/Annual Well Site Inspection Form

Section 1: General Information	
Operation Data	Inspection Data
Operator Name	Inspector Name
Snake River Oil + Gas, LLC	James Thum
Well Name	Area Office
ML Investments #2-10, USWN 11-075-20022 Authorized Contact Dan Johanek (208)800-9503	Boise / Director's Inspection Date
112 N. Plymouth, New Plymouth ID	11/13/2023 11:30 AM
County	Report Date
Payette	12/7/2023
Inspector's Signature:	Inspection Summary:
	\boxtimes Operation appeared to be in compliance at the time of
James Thum	the inspection.
	Issues of concern identified at the time of the
Date of Signature: 12/7/2023	inspection.
Location Description: 1800 feet ESE from Little Willow C	Gathering Facility, 4649 Little Willow Road. Google Maps
location Latitude 44.049326, Longitude -116.796756	
-	
Weather: Overcast, calm winds, 45°F	
Well is currently S/I and not producing.	C. 1 Lecture (L. Stranger)
Scope of Inspection (check all that apply and, or, were veri	
🛛 Well site 🔲 Tank Battery 🕅 W	ellhead 🖂 Meters 🗋 Other:
If well site, is the well a multiple zone completion?	🗌 Yes 🖾 No
Section 2: Pits	IDAPA 20.07.02.230
1. Are pits located on site?	Tyes X No
A. If yes;	
i. Permitted as:	Short-term pit 🗌 Long term pit
ii. Use Corresponding Pit Inspection Form and	attach with this inspection.
Section 3: Identification of Wells	IDAPA 20.07.02.300
1. Is a lease access road sign visible where the principa	al lease road enters the lease?
A. If yes;	
-	
i. Does the sign show:	
a. The name of the lease?	🖂 Yes 🛄 No
b. The name of the owner or operator?	🛛 Yes 🗌 No
c. The Section, Township and Range?	🛛 Yes 🗌 No
2. Is a legible well site sign visible near the well?	🛛 Yes 🗌 No
A. If yes;	
i. Does the well site sign identify the;	<u> </u>
a. Operator?	Yes 🗌 No
b. Permit number?	🖂 Yes 🗌 No
c. Well name?	🛛 Yes 🗌 No
d. Emergency telephone number?	\boxtimes Yes \square No
3. For multiple completions, is there a sign for each we	all bood connection?

Section 20.07.0	1 4: Location Operations	IDAPA	
1.	Is the well site fenced? (Answer N/A if the well has not been completed and fencing is not erected) A. If Yes;	🗌 N/A 🔀 Yes 🗌 No	
	i. Was the fence installed within 60 days of completing the facility?	🛛 Yes 🗌 No	
	ii. Does the fence appear to:		
	a. Maintain safe working conditions?	🖂 Yes 🗌 No	
	b. Secure the well site? Dual gates; south gate seldom used	🛛 Yes 🗌 No	
	c. Prevent access by wildlife and livestock?	🛛 Yes 🗌 No	
2.	Is there less than 5% vegetation on site?	🛛 Yes 🗌 No	
3.	Has it been more than six months since the removal of the drilling rig? A. If No;	🛛 Yes 🗌 No	
	i. Are chemicals stored and maintained in accordance with all applicable MSDS requirements?	🛛 N/A 🗌 Yes 🗌 No	
	ii. Are all materials related to operations palletized?	🛛 N/A 🗌 Yes 🗌 No	
	iii. Do all vehicles or materials on the site appear to be in use?	🛛 N/A 🗌 Yes 🗌 No	
	iv. Is the site free from all trash, debris, or scrap metal on site?	🛛 Yes 🗌 No	
	a. If no, is all trash, debris and scrap metal pending removal kept in a wind proof container and appear emptied regularly?	🔀 N/A 🗌 Yes 🗌 No	
	b. If trash or debris constitutes a fire hazard, is it removed to at least 100 feet from the facility, tanks or separators?	🛛 N/A 🗌 Yes 🗌 No	
	B. If Yes;		
	i. Are all debris and waste materials including, but not limited to, concrete, sack bentonite and other drilling mud additives, sand, plastic, pipe, and cable associated with the drilling and completion operations removed and disposed of properly?	🛛 Yes 🗌 No	
	 Are all disturbed areas affected by drilling or subsequent operations, except areas reasonably needed for production operations or subsequent drilling operations within twelve months, reclaimed and revegetated to approximately the pre-drilling condition (in accordance with IDAPA 20.07.02.510.04-07 or to the condition specified in an 		
	agreement with the surface owner.	🛛 Yes 🗌 No	
Section 20.07.0	1 5: Accidents and Fires	IDAPA	
	Is the emergency response plan available for use or inspection?	🛛 Yes 🗌 No	
	A. If yes, does the operation appear to be consistent with the response plan?	\square Yes \square No	
2. Is the location free of evidence of recent fires? \square			
	A. If no, have they been properly reported?	⊠ Yes ∐ No ⊠ N/A □ Yes □ No	

	3.	Ask for a spill prevention and countermeasures plan (SPCC can be located in company office). Are they aware of it?	🛛 Yes 🗌 No
		See Notes	
		n 6: Chokes 02.312	IDAPA
20.	1.	Are all flowing wells equipped with adequate chokes to properly control flow?	N/A Yes No
		n 7: Measurement of Gas 02.402	IDAPA
	1.	Is the site a natural gas well?	🛛 Yes 🗌 No
		A. If yes, is there a standard industry meter approved by the American Gas Associati and capable of recording accurately the volume of natural gas produced at each w	
		B. If no, is there another methodology being utilized that has been approved by the Department?	🛛 N/A 🗌 Yes 🗌 No
		a. If yes, describe:	
	2.	Separator location and Meter System Location:	
		n 8: Meters	IDAPA
20.		02.410	
	1.	Type of Hydrocarbon Measuring Systems:	
		Coriolis Measuring System for Liquids Drifice Measuring System for Gas	
	n	Other:	🛛 Yes 🗌 No
	2.	Are meter fittings of adequate size to measure gas efficiently? Are meters accessible and viewable? Tubing String Only	
	3. 4.	Are valves installed so pressures can be readily obtained on both casing and tubing?	⊠ Yes ∐ No ⊠ Yes ∏ No
		Are yearly meter calibration records available for inspection?	\square N/A \boxtimes Yes \square No
Sec	otio	n 9: Tank Batteries	IDAPA
		02.420	
	1.	Are there tank batteries located on site? A. If yes, are all tank batteries located at least 300 feet from any existing:	🗌 Yes 🛛 No
		i. Occupied structures?	Yes No
		ii. Water wells?	Yes No
		iii. Canals? NA- no tanks on site	Yes No
		iv. Ditches?	Yes No
		v. Natural or ordinary high water mark of surface waters?	Yes No
		B. Is location at least 50 feet from highways when measured from outermost portion of the tank dike?	🗌 Yes 🗌 No
		C. Are all tanks containing produced fluids or crude oil surrounded by tank dikes?	Yes No
		D. Are all tanks equipped to receive produced fluids surrounded by tank dikes?	Yes No
		i. If yes;	
		a. Do the dikes have a capacity of at least $1\frac{1}{2}$ times the volume of the large	st tank? 🗌 Yes 🗌 No

c. d. e. f.		Го То Го
Section 10: Inspe Comments and Is		
Section 5, Item 3: site but documents	SPCC documentation at New Plymouth office and Little Willow GF. SDS chemical documents on s are wet and cannot be removed from tube. Recommend that it be replaced.	
	A (no gauge installed) = NA (no gauge installed) psi	

Section 11: Attachments

List any and all attachments including photos, samples, documents, etc:

10 photos uploaded to the well files 11/30/2023

ML Investments #1-10 well head and internal security gate. View is Northwest



Chemical SDS paperwork is wet and cannot be removed from protective tubing. Recommend replacement.

