Post Drilling/Annual Well Site Inspection Form

Section 1: General Information	
Operation Data	Inspection Data
Operator Name	Inspector Name James Thum
Snake River Oil + Gas, LLC Well Name	Area Office
DJS Properties #1-15, USWN 11-075-20020	Boise – Director's
Authorized Contact Dan Johanek (208)800-9503	Inspection Date
112 N. Plymouth, New Plymouth ID	10/3/2024 12:00 PM
County	Report Date
Payette	10/16/2024
Inspector's Signature:	Inspection Summary:
James Thum	Operation appeared to be in compliance at the time of the inspection.
	☐ Issues of concern identified at the time of the
Date of Signature: 10/16/2024	inspection.
Location Description: 1.09 miles SSE from Little Willow Ga	athering Facility, 4649 Little Willow Road. Google Maps
location Latitude 44.034893, Longitude -116.800803	
Weather: 50° F, SW wind < 5 MPH, clear with high hazy clou	ds. Well S/I at time of inspection.
Scope of Inspection (check all that apply and, or, were verifie	d during the inspection):
If well site, is the well a multiple zone completion?	Yes ⊠ No
Section 2: Pits	IDAPA 20.07.02.230
	☐ Yes ⊠ No
1. Are pits located on site?	☐ Tes ☐ No
A. If yes;	
	Short-term pit
ii. Use Corresponding Pit Inspection Form and a	ttach with this inspection.
Well was drilled with closed loop mud system.	
Section 3: Identification of Wells	IDAPA 20.07.02.300
Is a lease access road sign visible where the principal leads to the principal leads t	
A. If yes;	rease road enters the rease.
i. Does the sign show:	
a. The name of the lease?	⊻ Yes ⊥ No
b. The name of the owner or operator?	∑ Yes ☐ No
c. The Section, Township and Range?	∑ Yes ☐ No
2. Is a legible well site sign visible near the well?	
A. If yes;	
i. Does the well site sign identify the;	
a. Operator?	⊠ Yes □ No
b. Permit number?	∑ Yes ☐ No
c. Well name?	∑ Yes ☐ No
d. Emergency telephone number?	∑ Yes ☐ No
3. For multiple completions, is there a sign for each well Section 4: Location Operations	head connection? N/A Yes No IDAPA 20.07.02.301

1.	Is the well site fenced? (Answer N/A if the well has not been completed and fencing is not erected) A. If Yes;	□ N/A ⊠ Yes □ No
	i. Was the fence installed within 60 days of completing the facility?	⊠ Yes □ No
	ii. Does the fence appear to:	
	a. Maintain safe working conditions?	∑ Yes ☐ No
	b. Secure the well site?	Yes □ No
	c. Prevent access by wildlife and livestock? Gate was open at time of inspe	ection
2.	Is there less than 5% vegetation on site?	Yes No
3.	Has it been more than six months since the removal of the drilling rig? A. If No;	Yes □ No
	i. Are chemicals stored and maintained in accordance with all	
	applicable MSDS requirements?	N/A ☐ Yes ☐ No
	ii. Are all materials related to operations palletized?	N/A ☐ Yes ☐ No
	iii. Do all vehicles or materials on the site appear to be in use?	⊠ N/A □ Yes □ No
	iv. Is the site free from all trash, debris, or scrap metal on site?	Yes □ No
	a. If no, is all trash, debris and scrap metal pending removal kept in a wind proof container and appear emptied regularly?	N/A ☐ Yes ☐ No
	b. If trash or debris constitutes a fire hazard, is it removed to at least 100 feet from the facility, tanks or separators?	N/A □ Yes □ No
	 B. If Yes; i. Are all debris and waste materials including, but not limited to, concrete, sack bentonite and other drilling mud additives, sand, plastic, pipe, and cable associated with the drilling and completion operations removed and disposed of properly? 	⊠ Yes □ No
	ii. Are all disturbed areas affected by drilling or subsequent operations, except areas reasonably needed for production operations or subsequent drilling operations within twelve months, reclaimed and revegetated to approximately the pre-drilling condition (in accordance with IDAPA 20.07.02.510.04-07 or to the condition specified in an	
	agreement with the surface owner.	∑ Yes □ No
Section	on 5: Accidents and Fires	IDAPA 20.07.02.302
1.	Is the emergency response plan available for use or inspection?	∑ Yes No
	A. If yes, does the operation appear to be consistent with the response plan?	⊠ Yes □ No
2.	Is the location free of evidence of recent fires?	Yes □ No
	A. If no, have they been properly reported?	N/A ☐ Yes ☐ No
3.	Ask for a spill prevention and countermeasures plan (SPCC can be located in company office). Are they aware of it?	∑ Yes No

Soati	on 6.	See No Chokes		DAPA 20.07.	02 212
Secure 1.					02.312 No
1.	All	e all Hov	wing wens equipped with adequate chokes to properly control flow?		INO
Section	on 7:	Measur	rement of Gas	DAPA 20.07.	02.402
1.	. Is t	he site a	natural gas well?	⊠ Yes □	No
	A.		is there a standard industry meter approved by the American Gas Association bable of recording accurately the volume of natural gas produced at each well?	⊠ Yes □	No
	В.		s there another methodology being utilized that has been approved by partment?	☐ Yes ☐	No
		a.	If yes, describe: NA		
2.	Se 	a	location and Meter System Location: Site		
Section	on 8:	Meters	II	DAPA 20.07.	02.410
1.	. Ty	pe of Hy	drocarbon Measuring Systems:		
	\boxtimes	Corioli	s Measuring System for Liquids Orifice Measuring System for Gas		
		Other:			
2.	. Ar	e meter f	fittings of adequate size to measure gas efficiently?	⊠ Yes □	No
3.	Ar	e meters	accessible and viewable?	⊠ Yes □	No
4.	. Ar	e valves	installed so pressures can be readily obtained on both casing and tubing?	⊠ Yes □	No
5.	. Ar	e yearly	meter calibration records available for inspection?	⊠ Yes □	No
Section	on 9:	Tank B	Satteries II	DAPA 20.07.	02.420
1.			ank batteries located on site? 3 tanks are all tank batteries located at least 300 feet from any existing:	⊠ Yes □	No
		i.	Occupied structures?	⊠ Yes □	No
		ii.	Water wells?	⊠ Yes □	No
		iii.	Canals?	∑ Yes □	No
		iv.	Ditches?	∑ Yes □	No
	D	V.	Natural or ordinary high water mark of surface waters? ion at least 50 feet from highways when measured from outermost	⊠ Yes □	No
			he tank dike?	⊠ Yes □	No
	C.	Are all	tanks containing produced fluids or crude oil surrounded by tank dikes?	⊠ Yes □	No
	D.	Are all	tanks equipped to receive produced fluids surrounded by tank dikes?	⊠ Yes □	No
		i.	If yes;		
		a.	Do the dikes have a capacity of at least 1 ½ times the volume of the largest tank?	☐ Yes ⊠	No
		b.	Is all piping and manmade improvements that perforate the dike wall or tank battery floor sealed to a minimum radius of 12" from outside edge of the piping or improvement?	Yes	No
		c.	Are valves and quick-connect couplers at least 18" from inside wall of tank dike?		No
		d.	Is vegetation on top and outside surface properly maintained?	☐ Yes ☐	

e. Is a ladder or other permanent device installed over the tank dike to access the containment reservoir?						
Section 10: Inspection Comments						
Comments and Issues of Concern:						
Section 5, Items #1 and #3: Emergency Response Plan and SPC located at Little Willow and New Plymouth company office.						
Section 9, Item #1.D.i.: Quick connect coupler is located outside of containment dike with installed spill containment device per current BMPs.						
Section 9, Item #1.D.i: 2023 containment dike dimensions indicate the volume to be 1.09 times the volume of the largest tank. Rule requirement per IDAPA 20.07.02.420.01.a is 1.5 times the volume of the largest tank.						
Section 9, Item #1.E. Northeast produced water tank open flow line needs capped. Petroleum smell detected.						
Other items: Leak tag dated 9/12/2024 noted on southwesternmost produced water tank thief hatch						
Tubing string: 1400 psi (analog) Production csg: 1220 psi (analog) Surface csg: NA Other: flow line from tbg string to separator: 9763 kPa, fluctuating higher and lower.						
Cellar is filled in with gravel, internal security fence around wellhead.						

Section 11: Attachments

List any and all attachments including photos, samples, documents, etc: 20 photos uploaded to well file 10/8/2024

Wellhead and internal security fence, foreground. Separator unit background. View is west.



SCADA system and solar panels (foreground), separator unit (left background), tank battery and wellhead (center background). View is north.



Barrels near separator unit need portable spill containment devices.

Thief hatch leak tag dated 9/12/2024, southwesternmost produced water tank. DETAILED LEAK INFORMATION CAN BE FOUND IN THE FOLLOW-UP EVENTS AFTER LEAK REPAIRED DOR REQUIRED

Northeasternmost produced water tank with open line needs capped. View is northeast.

Bladed firebreak around pad for protection from August 2024 Paddock Fire. View is Northeast up Little Willow Canyon along north perimeter of the well pad.

