

Post Drilling/Annual Well Site Inspection Form

Section 1: General Information	
Operation Data	Inspection Data
Operator Name Snake River Oil + Gas, LLC	Inspector Name James Thum
Well Name ML Investments #1-11, USWN 11-075-20025	Area Office Boise – Director’s office
Authorized Contact Dan Johaneke (208)800-9503 112 N. Plymouth, New Plymouth ID	Inspection Date 10/3/2024 10:50 AM
County Payette	Report Date 10/10/2024
Inspector’s Signature: <div style="text-align: center; font-family: cursive; font-size: 1.2em;">James Thum</div> Date of Signature: 10/10/2024	Inspection Summary: <input checked="" type="checkbox"/> Operation appeared to be in compliance at the time of the inspection. <input type="checkbox"/> Issues of concern identified at the time of the inspection.

Location Description: 3550 feet SE from Little Willow Gathering Facility, 4649 Little Willow Road. Google Maps location Latitude 44.045964, Longitude -116.791613. **Well declared inactive 8/15/2023** as a result of consecutive 24 months of no production. Plugging deadline extended to December 19, 2024.

Weather: 47°F, calm winds, high thin clouds

Scope of Inspection (check all that apply and, or, were verified during the inspection):

Well site Tank Battery Wellhead Meters Other:

If well site, is the well a multiple zone completion? Yes No

Section 2: Pits	IDAPA 20.07.02.230
-----------------	--------------------

- 1. Are pits located on site? Yes No
- A. If yes;
- i. Permitted as: Short-term pit Long term pit
- ii. Use Corresponding Pit Inspection Form and attach with this inspection.

Section 3: Identification of Wells	IDAPA 20.07.02.300
------------------------------------	--------------------

- 1. Is a lease access road sign visible where the principal lease road enters the lease? Yes No
- A. If yes;
- i. Does the sign show:
 - a. The name of the lease? Yes No
 - b. The name of the owner or operator? Yes No
 - c. The Section, Township and Range? Yes No
- 2. Is a legible well site sign visible near the well? Yes No
- A. If yes;
- i. Does the well site sign identify the;
 - a. Operator? Yes No
 - b. Permit number? Yes No
 - c. Well name? Yes No
 - d. Emergency telephone number? **1-870-234-3080** Yes No
- 3. For multiple completions, is there a sign for each well head connection? N/A Yes No

Section 4: Location Operations
20.07.02.301

IDAPA

1. Is the well site fenced?
(Answer N/A if the well has not been completed and fencing is not erected) N/A Yes No
- A. If Yes;
- i. Was the fence installed within 60 days of completing the facility? Yes No
- ii. Does the fence appear to:
- a. Maintain safe working conditions? Yes No
- b. Secure the well site? Yes No
- c. Prevent access by wildlife and livestock? Yes No
2. Is there less than 5% vegetation on site? Yes No
3. Has it been more than six months since the removal of the drilling rig? Yes No
- A. If No;
- i. Are chemicals stored and maintained in accordance with all applicable MSDS requirements? N/A Yes No
- ii. Are all materials related to operations palletized? N/A Yes No
- iii. Do all vehicles or materials on the site appear to be in use? N/A Yes No
- iv. Is the site free from all trash, debris, or scrap metal on site? Yes No
- a. If no, is all trash, debris and scrap metal pending removal kept in a wind proof container and appear emptied regularly? N/A Yes No
- b. If trash or debris constitutes a fire hazard, is it removed to at least 100 feet from the facility, tanks or separators? N/A Yes No
- B. If Yes;
- i. Are all debris and waste materials including, but not limited to, concrete, sack bentonite and other drilling mud additives, sand, plastic, pipe, and cable associated with the drilling and completion operations removed and disposed of properly? Yes No
- ii. Are all disturbed areas affected by drilling or subsequent operations, except areas reasonably needed for production operations or subsequent drilling operations within twelve months, reclaimed and revegetated to approximately the pre-drilling condition (in accordance with IDAPA 20.07.02.510.04-07 or to the condition specified in an agreement with the surface owner. Yes No

Section 5: Accidents and Fires
20.07.02.302

IDAPA

1. Is the emergency response plan available for use or inspection? Yes No
- A. If yes, does the operation appear to be consistent with the response plan? Yes No
2. Is the location free of evidence of recent fires? Yes No
- A. If no, have they been properly reported? N/A Yes No

3. Ask for a spill prevention and countermeasures plan (SPCC can be located in company office). Are they aware of it? Yes No

See Notes

Section 6: Chokes

IDAPA

20.07.02.312

1. Are all flowing wells equipped with adequate chokes to properly control flow? N/A Yes No

Section 7: Measurement of Gas

IDAPA

20.07.02.402

1. Is the site a natural gas well? S/I, not producing (inactive status) Yes No
- A. If yes, is there a standard industry meter approved by the American Gas Association and capable of recording accurately the volume of natural gas produced at each well? Yes No
- B. If no, is there another methodology being utilized that has been approved by the Department? N/A Yes No
- a. If yes, describe:
2. Separator location and Meter System Location:
 Well Site Little Willow Gathering Facility Other: _____

Section 8: Meters

IDAPA

20.07.02.410

1. Type of Hydrocarbon Measuring Systems:
 Coriolis Measuring System for Liquids Orifice Measuring System for Gas
 Other: _____
2. Are meter fittings of adequate size to measure gas efficiently? Yes No
3. Are meters accessible and viewable? Yes No
4. Are valves installed so pressures can be readily obtained on both casing and tubing? Yes No
5. Are yearly meter calibration records available for inspection? N/A Yes No

Section 9: Tank Batteries

IDAPA

20.07.02.420

1. Are there tank batteries located on site? Yes No
- A. If yes, are all tank batteries located at least 300 feet from any existing:
- i. Occupied structures? Yes No
- ii. Water wells? Yes No
- iii. Canals? **NA** Yes No
- iv. Ditches? Yes No
- v. Natural or ordinary high water mark of surface waters? Yes No
- B. Is location at least 50 feet from highways when measured from outermost portion of the tank dike? Yes No
- C. Are all tanks containing produced fluids or crude oil surrounded by tank dikes? Yes No
- D. Are all tanks equipped to receive produced fluids surrounded by tank dikes? Yes No
- i. If yes;
- a. Do the dikes have a capacity of at least 1 ½ times the volume of the largest tank? Yes No

- b. Is all piping and manmade improvements that perforate the dike wall or tank battery floor sealed to a minimum radius of 12” from outside edge of the piping or improvement? Yes No
- c. Are valves and quick-connect couplers at least 18” from inside wall of tank dike? Yes No
- d. Is vegetation on top and outside surface properly maintained? Yes No
- e. Is a ladder or other permanent device installed over the tank dike to access the containment reservoir? Yes No
- f. Is containment reservoir free of vegetation, storm water, produced fluids, other oil and gas field related debris, trash or flammable material? Yes No
- E. Do drain lines have a valve installed, closed and capped off if not in use? Yes No

Section 10: Inspection Comments

Comments and Issues of Concern:

Section 5: Emergency response plan and SPC are located at New Plymouth company office and Little Willow Gathering Facility. No chemicals are being stored or used on location.

Production casing: 0 PSI (analog)

Surface casing: NA

LT tubing string= 300 psi (analog)

UT tubing string= 0 psi (analog)

Digital gauges are on site but have been uninstalled.

Cellar is open (not gravel filled) and dry.

Section 11: Attachments

List any and all attachments including photos, samples, documents, etc: 14 photos, uploaded to well files
10/8/2024

Dual completion wellhead with UT completion on the right, LT completion on the left. Open cellar (not gravel-filled) with safety grate over cellar. View is northwest.



View of production casing gauge and cellar on UT completion side.



UT tubing string gauge on left (0 psi), LT tubing string gauge on right (300 psi).

