


Post Drilling/Annual Well Site Inspection Form

Section 1: General Information	
Operation Data Operator Name Snake River Oil + Gas, LLC Well Name Fallon #1-11, USWN 11-075-20037 Authorized Contact Dan Johaneck (208)800-9503 112 N. Plymouth, New Plymouth ID; Tyler Hartung (208) 412-5475 County Payette Inspector's Signature:  Date of Signature: 9/23/2025	Inspection Data Inspector Name James Thum / Derek Kraft Area Office Boise – Director's / Southwest Supervisory Area Inspection Date 4/21/2025 1:30 PM Report Date 5/17/2025 Inspection Summary: ☐ Operation appeared to be in compliance at the time of the inspection. ☒ Issues of concern identified at the time of the inspection.
Location Description: 1.0 miles NE from Hwy 30 and Hwy 95 intersection in Fruitland, ID, east of Hwy 95 north side of Killebrew Road, north of the Payette River. Google Maps location Latitude 44.040984, Longitude -116.906820. Well is currently producing as of 2/11/2022 but was shut-in on day and time of inspection. Weather: partly cloudy, light north wind, 70°F.	
Scope of Inspection (check all that apply and, or, were verified during the inspection): ☒ Well site ☐ Tank Battery ☒ Wellhead ☒ Meters ☐ Other: If well site, is the well a multiple zone completion? ☐ Yes ☒ No	
Section 2: Pits IDAPA 20.07.02.230	
1. Are pits located on site? ☐ Yes ☒ No A. If yes; Well drilled with Paul Graham #4 rig, closed loop mud system i. Permitted as: ☐ Short-term pit ☐ Long term pit ii. Use Corresponding Pit Inspection Form and attach with this inspection.	
Section 3: Identification of Wells IDAPA 20.07.02.300	
1. Is a lease access road sign visible where the principal lease road enters the lease? ☒ Yes ☐ No A. If yes; i. Does the sign show: a. The name of the lease? ☒ Yes ☐ No b. The name of the owner or operator? ☒ Yes ☐ No c. The Section, Township and Range? ☒ Yes ☐ No 2. Is a legible well site sign visible near the well? ☒ Yes ☐ No A. If yes; i. Does the well site sign identify the; a. Operator? ☒ Yes ☐ No b. Permit number? ☒ Yes ☐ No	

c. Well name?	☒ Yes ☐ No
d. Emergency telephone number?	☒ Yes ☐ No
3. For multiple completions, is there a sign for each well head connection?	☒ N/A ☐ Yes ☐ No
Section 4: Location Operations	IDAPA 20.07.02.301
1. Is the well site fenced? (Answer N/A if the well has not been completed and fencing is not erected)	☐ N/A ☒ Yes ☐ No
A. If Yes;	
i. Was the fence installed within 60 days of completing the facility?	☒ Yes ☐ No
ii. Does the fence appear to:	
a. Maintain safe working conditions?	☒ Yes ☐ No
b. Secure the well site?	☒ Yes ☐ No
c. Prevent access by wildlife and livestock?	☒ Yes ☐ No
2. Is there less than 5% vegetation on site?	☒ Yes ☐ No
3. Has it been more than six months since the removal of the drilling rig?	☒ Yes ☐ No
A. If No;	
i. Are chemicals stored and maintained in accordance with all applicable MSDS requirements?	☐ N/A ☒ Yes ☐ No
ii. Are all materials related to operations palletized?	☒ N/A ☐ Yes ☐ No
iii. Do all vehicles or materials on the site appear to be in use?	☒ N/A ☐ Yes ☐ No
iv. Is the site free from all trash, debris, or scrap metal on site?	☒ Yes ☐ No
a. If no, is all trash, debris and scrap metal pending removal kept in a wind proof container and appear emptied regularly?	☒ N/A ☐ Yes ☐ No
b. If trash or debris constitutes a fire hazard, is it removed to at least 100 feet from the facility, tanks or separators?	☒ N/A ☐ Yes ☐ No
B. If Yes;	
i. Are all debris and waste materials including, but not limited to, concrete, sack bentonite and other drilling mud additives, sand, plastic, pipe, and cable associated with the drilling and completion operations removed and disposed of properly?	☒ Yes ☐ No
ii. Are all disturbed areas affected by drilling or subsequent operations, except areas reasonably needed for production operations or subsequent drilling operations within twelve months, reclaimed and revegetated to approximately the pre-drilling condition (in accordance with IDAPA 20.07.02.510.04-07 or to the condition specified in an agreement with the surface owner.	☒ Yes ☐ No
Section 5: Accidents and Fires	IDAPA 20.07.02.302
1. Is the emergency response plan available for use or inspection?	☒ Yes ☐ No
A. If yes, does the operation appear to be consistent with the response plan?	☒ Yes ☐ No
2. Is the location free of evidence of recent fires?	☒ Yes ☐ No
A. If no, have they been properly reported?	☒ N/A ☐ Yes ☐ No

3. Ask for a spill prevention and countermeasures plan (SPCC can be located in company office). Are they aware of it?

☒ Yes ☐ No

ERP, SPC available at New Plymouth office, Little Willow

Section 6: Chokes

IDAPA 20.07.02.312

1. Are all flowing wells equipped with adequate chokes to properly control flow?

☐ N/A ☒ Yes ☐ No

Section 7: Measurement of Gas

IDAPA 20.07.02.402

1. Is the site a natural gas well?

☒ Yes ☐ No

- A. If yes, is there a standard industry meter approved by the American Gas Association and capable of recording accurately the volume of natural gas produced at each well?

☒ Yes ☐ No

- B. If no, is there another methodology being utilized that has been approved by the Department?

☒ N/A ☐ Yes ☐ No

- a. If yes, describe:

2. Separator location and Meter System Location:

☒ Well Site ☐ Little Willow Gathering Facility ☐ Other: _____

Section 8: Meters

Idaho Code § 47-322, IDAPA 20.07.02.410

1. Type of Hydrocarbon Measuring Systems:

☒ Coriolis Measuring System for Liquids ☐ Orifice Measuring System for Gas

☐ Other: _____

2. Are meter fittings of adequate size to measure gas efficiently?

☒ Yes ☐ No

3. Are meters accessible and viewable?

☒ Yes ☐ No

4. Are valves installed so pressures can be readily obtained on both casing and tubing?

☒ Yes ☐ No

5. Are quarterly meter calibration records available for inspection?

☐ N/A ☒ Yes ☐ No

Section 9: Tank Batteries

IDAPA 20.07.02.420

1. Are there tank batteries located on site?

☐ Yes ☒ No

- A. If yes, are all tank batteries located at least 300 feet from any existing:

- i. Occupied structures?

☐ Yes ☐ No

- ii. Water wells?

☐ Yes ☐ No

- iii. Canals? N/A

☐ Yes ☐ No

- iv. Ditches?

☐ Yes ☐ No

- v. Natural or ordinary high water mark of surface waters?

☐ Yes ☐ No

- B. Is location at least 50 feet from highways when measured from outermost portion of the tank dike?

☐ Yes ☐ No

- C. Are all tanks containing produced fluids or crude oil surrounded by tank dikes?

☐ Yes ☐ No

- D. Are all tanks equipped to receive produced fluids surrounded by tank dikes?

☐ Yes ☐ No

- i. If yes;

- a. Do the dikes have a capacity of at least 1 ½ times the volume of the largest tank? ☐ Yes ☐ No

- b. Is all piping and manmade improvements that perforate the dike wall or tank battery floor sealed to a minimum radius of 12" from outside edge of the piping

or improvement?	☐ Yes ☐ No
c. Are valves and quick-connect couplers at least 18" from inside wall of tank dike?	☐ Yes ☐ No
d. Is vegetation on top and outside surface properly maintained?	☐ Yes ☐ No
N/A – no tank batteries	
e. Is a ladder or other permanent device installed over the tank dike to access the containment reservoir?	☐ Yes ☐ No
f. Is containment reservoir free of vegetation, storm water, produced fluids, other oil and gas field related debris, trash or flammable material?	☐ Yes ☐ No
E. Do drain lines have a valve installed, closed and capped off if not in use?	☐ Yes ☐ No

Section 10: Inspection Comments

Comments and Issues of Concern:

Small leak on surface casing pressure gauge (analog; shows 0 PSI); bubbling noted with soapy water test.

Temporary use of blue extension cords- power running from light post west of gate to separator unit.

Pressure readings:

Tubing string: 992 PSI (digital)

Production csg: 0 PSI (analog)

Surface csg: 0 PSI (analog)

Section 11: Attachments

List any and all attachments including photos, samples, documents, etc:

8 photos taken, uploaded to well files on the M drive.



Right side interior of separator unit.



Left side interior of separator unit, coriolis flow meter at lower right.



Analog pressure gauge for surface casing with small leak. Note pressure indicated as 0 PSI.



Blue extension cord as temporary power from separator unit to electric service box at pad gate.