

Idaho Department of Land
SUNDRY NOTICES AND REPORTS ON WELLS

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Well Permit Number 11-075-20029
2. Name of Operator Alta Mesa Services, LP		6. If Indian, Allottee or Tribe Name N/A
3a. Address 15021 Katy Freeway, Suite 400, Houston, TX 77094	3b. Phone No. (include area code) 281-530-0991	7. If Unk or CA/Agreement, Name and/or No. N/A
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Section 3 Township 8N Range 4W		8. Well Name and No. ML Investments #2-3
		9. API Well No. 11-075-20029
		10. Field and Pool, or Exploratory Area Willow
		11. County or Parish, State Payette, Idaho

CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> New Construction	<input type="checkbox"/> Stimulation Treat
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Production (Start/Resum)	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
	<input type="checkbox"/> Deepen	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other run slickline

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones, attach the Bond under which the work will be performed or provide the Bond No. on file with IDL. Required subsequent reports shall be filed within 30 days following completion of the involved operations. Final Abandonment Notices shall be filed only after operations. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

- MIRU 0.108" WL Wire-Tech quick rig 3LU w/ SK pressure control.
- Take pressures - SHTP / SICP / SSCP
- ISA
- MU 1.5" SB and jar Assy.
- Open well to lub and equalize same.
- Check for leaks (proceed if no leaks).
- RIH w/ 1.75" sample beller and tag bottom (PBTD 4705').
- POOH - Note FL and recovery if any.
- MU 1.25" tandem memory press/temp gauges w/ jar Assy.
- Open well and equalize lub.
- Check for leaks (proceed if no leaks).
- Make 5 min stop at surface.
- RIH making 5 min stops every 500' to 4488'.
- Take 30 mins reading at 4488'.
- POOH making 5 min stops every 500' including surface stop.
- Confirm data is good on memory gauges and downloaded same.
- SWI

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	Title Regulatory Analyst
Signature <i>Jimmy Shrest</i>	Date May 9, 2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE	
Approved by <i>James [Signature]</i>	Date May 10, 2018
Title JOE Program Manager	Office Boise

*Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

BOISE, IDAHO
2018 MAY 10 AM 9:48
DEPT. OF LANDS