

Idaho Department of Land

SUNDRY NOTICES AND REPORTS ON WELLS

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Well Permit Number LU600026
2. Name of Operator Alta Mesa Services, LP		6. If Indian, Allottee or Tribe Name N/A
3a. Address 15021 Katy Freeway, Suite 400, Houston, TX 77094	3b. Phone No. (include area code) 281-530-0991	7. If Unit or CA/Agreement, Name and/or No. N/A
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) S2 T7N R4W 2033' FSL 647' FWL		8. Well Name and No. WHITE #1-10 Tracy Trust #3-2
		9. API Well No. 20-011 11-075-20013
		10. Field and Pool, or Exploratory Area Hamilton
		11. County or Parrish, State Payette, Idaho
CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> New Construction
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Plug and Abandon
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Plug Back
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Production (Start/Resume)
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Deepen	<input type="checkbox"/> Recomplete
		<input type="checkbox"/> Stimulation Treat
		<input type="checkbox"/> Temporarily Abandon
		<input type="checkbox"/> Water Disposal
		<input type="checkbox"/> Water Shut-Off
		<input type="checkbox"/> Well Integrity
		<input checked="" type="checkbox"/> Other <u>Slickline survey - pressure / PBTD</u>

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones, attach the Bond under which the work will be performed or provide the Bond No. on file with IDL. Required subsequent reports shall be filed within 30 days following completion of the involved operations. Final Abandonment Notices shall be filed only after operations. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

(Phase 1 of potentially 3 phases:)

Move in wireline unit. Run gauge ring tools to determine plug back total depth and to determine any restrictions in the wellbore.

Take downhole pressure and temperature measurements to determine static bottom hole pressure and temperature.

Run sample bailers, as necessary to collect samples of wellbore materials for analysis.

Phase 2 and Phase 3, of planned work, will be to move in workover rig and/or flow test the well. Future Sundry Notices will detail those plans as they become visible, based on the results and analysis of Phase 1.

14. I hereby certify that the foregoing is true and correct	
Name (Printed/Typed) Dale R. Hayes	Title VP - Operations
Signature <i>Dale R. Hayes</i>	Date 9/11/2012

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by <i>Stewart D. Taylor</i>	Date 9/25/12
Title Area Manager	Office Southwest

*Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.